

735 Baillie Avenue, Kelowna, V1Y 7E9 Tel: 250 763 4911

	V
Technician: Kendall Date: 15/8/23	
Customer Name: PATTON MOTORCARS	
Yr./Make/Model: 2010 nissan altima	
VIN: IN4BLZEP4AC149728	
Villeage: 237, 360 Repair Order #: 3266	
BRAKE AND TIRE Left Front Right Front	
Brake Lining 4 mm Brake Lining 4 mm	
Tire Tread32nds	
Tire Pressure PSI Tire Pressure PSI	
Rotor / Drum Rotor / Drum	
Alignment Check Needed Wheel Balance Needed	
Left Rear Right Rear	
Brake Lining 8 mm Brake Lining 8 mm Tire Tread 7 3/2nds Tire Tread 7 3/2nds	
Wear Pattern Wear Pattern	
Tire Pressure PSI Before After Before After	
Rotor / Drum Rotor / Drum	
Brake Inspection Not Performed This Visit	
PRIOR BODY DAMAGE	
	ULL
X X CHSTOMER ACKNOWLEDGMENT	
COMMENTS / ESTIMATES	
	Pass

